




1 mA JUMPER
Pull this jumper and place a current meter (DVM) in series to measure actual mA